

Change Notice Form

Change Notice #	Date of Notice	Distribution: <input checked="" type="checkbox"/> General <input type="checkbox"/> Customer Specific
PCN036	October 19 2018	Post Change Notice to Website? <input checked="" type="checkbox"/> yes <input type="checkbox"/> no

Title: Assembly & Test Capacity Expansion for the AT25DF641A & AT45DB641E DFN PACKAGE

Products Affected: See Appendix I for a list of complete part numbers.
Contact pcn@adestotech.com for an .XLS download of affected part numbers.

Change Type:

Document only Mat'l/Composition Manufacturing Process
 Manufacturing Location Quality/Reliability Logistics Design
 EOL/Product Discontinuance

Qualification Report Available:	12/31/2018	<input type="checkbox"/> not applicable
Product Sample:	10/19/2018	<input type="checkbox"/> not applicable
Target Production Release:	1/19/2019	

Last Time Buy:	Click here to enter a date.	<input checked="" type="checkbox"/> not applicable
Last Time Ship Date:	Click here to enter a date.	<input checked="" type="checkbox"/> not applicable

Sites Affected:	<input checked="" type="checkbox"/> None	Description:
Impact on Quality and Reliability	<input checked="" type="checkbox"/> None	Description:
Traceability of Change	<input type="checkbox"/> not applicable	<input checked="" type="checkbox"/> Product Mark <input type="checkbox"/> Date Code

Description of Change:
 Adesto will be adding Greatek Taiwan for assembly and final electrical test services for products listed in Appendix I.

Address all inquiries, including acceptance of this change, requests for qualification data and/or product samples to PCN@adestotech.com

Adesto will deem this change accepted, unless specific written conditions of acceptance are provided by the customer, within 30 days from the date of this notice. Adesto reserves the right to ship either the original version or the new version of the affected product after the Target Production Release Date specified in this notice.

APPENDIX I Affected Products (insert here)

Please refer to the table below for the part numbers affected.

AT45DB641E-MHN-Y

AT45DB641E-MHN-T

AT45DB641E-MHN2B-T

AT25DF641A-MH-Y

AT25DF641A-MH-T