# Release Notes DA16200 FreeRTOS SDK

## **Abstract**

This document contains the release notes for Dialog Semiconductor's DA16200 FreeRTOS Software Development Kit, version 3.1.1.0



# **Contents**

Ab	stract			1
Со	ntents	S		2
Tal	bles			2
1	Term	s and De	finitions	3
2	Relea	ase Data .		3
3				
4	Relea	ated Doci	umentation and References	3
5	Relea	ase Desc	ription	4
•	5.1		3.1.1.0	
	• • •	5.1.1	Overview	
		5.1.2	New and Updated Features of 3.1.0.0	
		5.1.3	Fixes and Improvements since 3.1.1.0	
6	Relea	ase Histo	ry	5
	6.1		3.1.0.0	
		6.1.1	Overview	5
		6.1.2	New and Updated Features of 3.1.0.0	5
		6.1.3	Fixes and Improvements since 3.1.0.0	5
		6.1.4	Known Issue of 3.1.0.0	5
		6.1.5	Known Limitations of 3.1.0.0	6
	6.2	Version	3.0.0.0	
		6.2.1	Overview	7
		6.2.2	New and Updated Features of 3.0.0.0	7
Аp	Appendix A Software Versioning Rules			
Do	cume	nt Revisi	on History	8
Ta	ables	5		
Tal Tal Tal Tal Tal	ble 2: 3 ble 3: 3 ble 4: 3 ble 5: 3 ble 6: 3	3.1.1.0 Ne 3.1.1.0 Fix 3.1.0.0 Ne 3.1.0.0 Fix 3.1.0.0 Kr	ew Features  Exes and Improvements  Exes and Improvements  Exes and Improvements  Exes and Improvements	4 4 5 5 5
			nown Limitationsew Features	



## 1 Terms and Definitions

API Application Programming Interface

OTA Over The Air Upgrade

RTOS Real Time Operating System
SDK Software Development Kit
QFN Quad Flat No-lead Package

#### 2 Release Data

## **Table 1: Information Table**

Software	SDK 3.1.1.0 ( DA16200 FreeRTOS SDK )
Device Number	DA16200
Software Release Date	11 May 2021
Software Version Number	3.1.1.0
Software Release Type (Note 1)	FULL (GA)

**Note 1** Releases can be of the following types: FULL (GA), FULL (LA), ENGINEERING, PATCH or BINARY

#### 3 License

Licenses covering this SDK release are listed in the license.txt file in SDK docs folder.

## 4 Releated Documentation and References

- [1] UM-WI-049, DA16200, FreeRTOS, SDK Startup Guide for Linux, Rev 1.0, User Manual, Dialog Semiconductor.
- [2] UM-WI-050, DA16200, FreeRTOS, SDK Startup Guide for Window, Rev 1.0, User Manual, Dialog Semiconductor.
- [3] UM-WI-046, DA16200, FreeRTOS, Programmer Guide, Rev 1.0, User Manual, Dialog Semiconductor
- [4] UM-WI-047, DA16200, FreeRTOS, EVK User Guide, Rev 1.0, User Manual, Dialog Semiconductor
- [5] UM-WI-048, DA16200, FreeRTOS, OTA User Guide, Rev 1.0, User Manual, Dialog Semiconductor
- [6] UM-WI-003, DA16200, AT-CMD User Guide, Rev 2.3, User Manual, Dialog Semiconductor
- [7] UM-WI-010, DA16200, MQTT Programmer Guide, Rev 1.6, User Manual, Dialog Semiconductor
- [8] DA16200, Datasheet, Rev 3.2, Datasheet, Dialog Semiconductor.



# **5** Release Description

#### 5.1 Version 3.1.1.0

#### 5.1.1 Overview

This is a full release of SDK V3.1.1.0 which supports the DA16200 device It adds DPM daemon and related functions support for the DA16200. Also, adds several improvements and fixes as listed in the following tables.

## 5.1.2 New and Updated Features of 3.1.1.0

#### Table 2: 3.1.1.0 New Features

Featrure Number	Description
3.1.0.0 - 01	None

## 5.1.3 Fixes and Improvements since 3.1.1.0

## Table 3: 3.1.1.0 Fixes and Improvements

Fix Number	Description
3.1.1.0 / 01	Fix first "ping domain_url" operation error after POR booting.
3.1.1.0 / 02	Fix Http Client Sample build error.



# **6** Release History

#### 6.1 Version 3.1.0.0

#### 6.1.1 Overview

This is a full release of SDK V3.1.0.0 which supports the DA16200 device It adds DPM daemon and related functions support for the DA16200. Also, adds several improvements and fixes as listed in the following tables.

## 6.1.2 New and Updated Features of 3.1.0.0

#### Table 4: 3.1.0.0 New Features

Featrure Number	Description
3.1.0.0 - 01 Support for DPM operation to FreeRTOS SDK package.	
3.1.0.0 - 02 Merge pTIM and RamLib binary into RTOS binary FW image.	
3.1.0.0 - 03	Add the function to break for endless loop reboot when exception event occurs.  - To break boot sequence when power-on-reboot, press <esc> key on Console terminal utility.  - Auto break when 5 times of exception events occur on the same PC (Program count).</esc>
3.1.0.0 - 04	Support for Adesto SFLASH device AT25SL321 and GigaDevice GD25LQ16C SFLASH device.

## 6.1.3 Fixes and Improvements since 3.1.0.0

## Table 5: 3.1.0.0 Fixes and Improvements

Fix Number	Description
3.1.0.0 / 01	Initial official SDK version. No fix and improvement information.

#### 6.1.4 Known Issue of 3.1.0.0

#### Table 6: 3.1.0.0 Known Issues

Issue Number	Description
3.1.0.0 : 01	When connecting the legacy-AP(AX1500) set to "Hidden SSID" mode, a beaconchange event occurs and it is the reason of "Network Interface(wlan0): DONW" error.
3.1.0.0 : 02	In AT-CMD, when "AT+WFAPCH" command run, it does not change to new channel value but it looks like it has changed as new channel value.
3.1.0.0 : 03	Some AT-CMDs, it is needed to add validity check function about parameters.
3.1.0.0 : 04	Some compiled warning messages remain in the Eclipse IDE.



## 6.1.5 Known Limitations of 3.1.0.0

## Table 7: 3.1.0.0 Known Limitations

Issue Number	Description
3.1.0.0 :: 01 Not support AT-CMD feature on 2MB SFLASH type.	
3.1.0.0 :: 02	Not support secure mode / RMA mode booting.
3.1.0.0 :: 03	Performance test : Recommended iPerf tool version 2.0.5.
3.1.0.0 :: 04	Not support multi-session connection on TCP/UDP server
3.1.0.0 :: 05	Not support WPA3 functions in V 3.1.0.0 SDK.



#### 6.2 Version 3.0.0.0

#### 6.2.1 Overview

This is a full release of SDK 3.0.0.0 which supports the DA16200 device. This version is initial version to support FreeRTOS™, IwIP network stack and Eclipse IDE w/ GCC compiler.

## 6.2.2 New and Updated Features of 3.0.0.0

Table 8: 3.1.0.0 New Features

Featrure Number	Description
3.0.0.0 - 01	Initial version for FreeRTOS kernel with IwIP network stack.

# **Appendix A Software Versioning Rules**

This describes the software version numbers and does not apply to documentation version numbers (as found in the footer of this document).

Each software version number string consists of four numbers: MAJOR. MINOR. REVISION. and ENGINEERING REV.

#MAJOR: It is increased (by one only) if the project undergoes a major modification, for example OS changes. It usually changes only when the project sources undergo major restructuring affecting most of the repository. It is initialized at 1.

#MINOR: Used in the case of concurrent projects that for special reasons need to be spun off the major repository. It corresponds to different versions of the repository code that have to be supported concurrently. In this case each branch number corresponds to a different GIT branch. The basic project has BRANCH id 0.

#REVISION: Full release versions. Each Full release increases this number by one. After the Full release, the number is inclrased by one again. Therefore, Project releases correspond to release numbers like X.Y.0.0, X.Y.1.0. etc. The #REVISION number is initialized at 0.

#ENGINEERING\_REV: The # ENGINEERING\_REV number increases by one at engineering update and thus indicates the total number of release since release the official SDK package. The ENGINEERING\_VERSION number is initialized at 0.



# **Document Revision History**

This section summarizes the changes made to this document and not to the Software that this document describes.

Revision	Date	Description
3	11-May-2021	Full Release 3.1.1.0
Change de	etails:	
- Bug fixes	first "ping domain	_url" operation after POR booting.
2	14-APR-2021	Full Release 3.1.0.0
Change de	etails:	
- Add new	features for DPM	operation
- Bug fixes	and internal impr	ovements
		Initial version. Official release for FreeRTOS SDK 3.0.0.0
		Documents
		- DA16200_FreeRTOS_SDK_Start_Guide_for_Linux_Rev_1v0.pdf
		- DA16200_FreeRTOS_SDK_Start_Guide_for_Windoes_Rev_1v0.pdf
1	18-Dec-2020	- DA16200_FreeRTOS_EVK_User_manual_Rev_1v0.pdf
		- DA16200_FreeRTOS_SDK_Programmer_User_manual_Rev_1v0.pdf
		- DA16200_FreeRTOS_AT-Command_User_Manual_Rev_1v0.pdf
		- DA16200_FreeRTOS_Example_Application_Manual_Rev_1v0.pdf
		- DA16200_FreeRTOS_MQTT_User_Manual_1v0.pdf
		- DA16200_FreeRTOS_OTA_update_User_Manual_1v0



#### **Status Definitions**

Status	Definition Definition	
DRAFT  The content of this document is under review and subject to formal approval, which may result in madditions.		
APPROVED or unmarked	The content of this document has been approved for publication.	

#### **Disclaimer**

Unless otherwise agreed in writing, the Dialog Semiconductor products (and any associated software) referred to in this document are not designed, authorized or warranted to be suitable for use in life support, life-critical or safety-critical systems or equipment, nor in applications where failure or malfunction of a Dialog Semiconductor product (or associated software) can reasonably be expected to result in personal injury, death or severe property or environmental damage. Dialog Semiconductor and its suppliers accept no liability for inclusion and/or use of Dialog Semiconductor products (and any associated software) in such equipment or applications and therefore such inclusion and/or use is at the customer's own risk.

Information in this document is believed to be accurate and reliable. However, Dialog Semiconductor does not give any representations or warranties, express or implied, as to the accuracy or completeness of such information. Dialog Semiconductor furthermore takes no responsibility whatsoever for the content in this document if provided by any information source outside of Dialog Semiconductor.

Dialog Semiconductor reserves the right to change without notice the information published in this document, including, without limitation, the specification and the design of the related semiconductor products, software and applications. Notwithstanding the foregoing, for any automotive grade version of the device, Dialog Semiconductor reserves the right to change the information published in this document, including, without limitation, the specification and the design of the related semiconductor products, software and applications, in accordance with its standard automotive change notification process.

Applications, software, and semiconductor products described in this document are for illustrative purposes only. Dialog Semiconductor makes no representation or warranty that such applications, software and semiconductor products will be suitable for the specified use without further testing or modification. Unless otherwise agreed in writing, such testing or modification is the sole responsibility of the customer and Dialog Semiconductor excludes all liability in this respect.

Nothing in this document may be construed as a license for customer to use the Dialog Semiconductor products, software and applications referred to in this document. Such license must be separately sought by customer with Dialog Semiconductor.

All use of Dialog Semiconductor products, software and applications referred to in this document is subject to Dialog Semiconductor's Standard Terms and Conditions of Sale, available on the company website (www.dialog-semiconductor.com) unless otherwise stated.

Dialog, Dialog Semiconductor and the Dialog logo are trademarks of Dialog Semiconductor Plc or its subsidiaries. All other product or service names and marks are the property of their respective owners.

© 2021 Dialog Semiconductor. All rights reserved

# **Contacting Dialog Semiconductor**

United Kingdom (Headquarters)

Dialog Semiconductor (UK) LTD Phone: +44 1793 757700

Germany

Dialog Semiconductor GmbH Phone: +49 7021 805-0

The Netherlands

Dialog Semiconductor B.V. Phone: +31 73 640 8822

Email:

enquiry@diasemi.com

North America

Dialog Semiconductor Inc. Phone: +1 408 845 8500

Janan

Dialog Semiconductor K. K. Phone: +81 3 5769 5100

Taiwan

Web site:

Dialog Semiconductor Taiwan Phone: +886 281 786 222

www.dialog-semiconductor.com

Hong Kong China

Dialog Semiconductor Hong Kong Phone: +852 2607 4271

Korea

Dialog Semiconductor Korea Phone: +82 31 785 8620 China (Shenzhen)

Dialog Semiconductor China Phone: +86 755 2298 6778

China (Shanghai)

Dialog Semiconductor China Phone: +86 21 2411 2011

Release Note Revision 3 11-May-2021